




10	0211 1965 27	2	HEX SOCK SCREW	MC6S M4x18 H 12.9
9	4230 2645 10	1	CABLE RAIL	QST 50
8	4230 1480 00	1	GREASE	KERNITE Lubra K HS*
7	4230 2128 00	1	COMPRESSION SPRING	20-30N Tra.3''
6	4230 2129 00	1	COMPRESSION SPRING	38-51N Tra.3''
5	4230 2127 00	1	SOCKET HOLDER	1/2" ±0mm 3" travel QM5 thru hole
4	4230 2711 80	1	FRONT PART	QST50, TRA 3''
3	4230 2973 80	1	TRANSDUCER	QDT50-100
2	4230 2171 80	1	GEAR UNIT	ETX50 ''50'' : i=18.21= (((36/14)+1)*((41/10)+1)))
1	4230 3012 80	1	MOTOR	QST 50
Pos	Designation	Number	Name	Comment

Tolerances, if not indicated, according to:	-	-	-	-	-
AC-STD	-	-	-	-	-

Name QST50-90CT-T76-L200-H13				Secrecy class -	
Material -				1102 K/-	
-				CAD Pro/E	
Scale 1:2		Format A3	Family MK2_G 3	Compare -	Drawing owner
Drawn JLT		Blank -		Replaces	T00
Cons.class 1295 K/-		Rev 3	Status RELEASED	Designation Sheet 1 (2)	
Transferred from -		Mass/Volume 6.5 kg		Date 2007-07-04	
8435 6040 11					



3	-	New connector: Motor & Transducer replaced = MK2	2013-03-07	ASH
Note	Pos.	Modified from	Date	Intr.

Model name	8435604011	Rev.Ver	3.0+
Drawing name	8435604011	Rev.Ver	3.1

This document is our property and shall not without our permission be altered, copied, used for manufacturing or communicated to any other person or company.

3	-	New connector: Motor & Transducer replaced = MK2	2013-03-07	ASH
Note	Pos.	Modified from	Date	Intr.

Tolerances, if not indicated, according to:				-	-	-	-	-
AC-STD				-	-	-	-	-
Name QST50-90CT-T76-L200-H13							Secrecy class	
Material -							1102 K/-	
-							CAD Pro/E	
<i>Atlas Copco</i>		Scale 1:2	Format A3	Family MK2_G		Compare -		Drawing owner
Drawn JLT			Blank -		Replaces		TOO	
Transferred from -		Cons.class 1295 K/-	Rev 3	Status RELEASED		Designation		Sheet 2 (2)
		Mass/Volume 6.5 kg		Date 2007-07-04		8435 6040 11		



HOLES MUST BE DRILLED IN BASE PLATE FOR OUTSIDE FITTED FRONT PART.

