





* FOR GREASE INSTRUCTIONS SEE PZ4113

Strongest compression spring mounted at delivery

Comment: Max torque 230Nm. Max speed 330 rpm.

10	4230 1480 00	1	GREASE	KERNITE Lubra K HS*
9	0211 1965 27	2	HEX SOCK SCREW	MC6S M4x18 H 12.9
8	4230 2647 10	1	CABLE RAIL	QST 62
7	4230 2135 00	1	COMPRESSION SPRING	45-59N Tra.3''
6	4230 2128 00	1	COMPRESSION SPRING	20-30N Tra.3''
5	4230 2137 00	1	SOCKET HOLDER	3/4" Tra.3"
4	4230 2712 80	1	FRONT PART	QST62 3"
3	4230 2974 80	1	TRANSDUCER	QDT62-200
2	4230 2172 81	1	GEAR UNIT	QMX62 l=19.04 = ((41/15+1)*(41/10+1))
1	4230 3013 80	1	MOTOR	QST 62

Pos	Designation	Number	Name	Comment
	Tolerances, if not indicated, according to:	-	-	-
	AC-STD	-	-	-

Name QST62-230CT-T76-L200-H19				QST		Secrecy class	
Material -				1102 K/-			
-				CAD Pro/E			
		Scale 9:20	Format A3	Family MK2_G	Compare -		Drawing owner TOO
		Drawn JLT		Blank -	Replaces		
Transferred from SW		Cons.class 1295 K/-	Rev 3	Status RELEASED	Designation		Sheet 1 (2)
		Mass/Volume 11.2 kg	Date 2007-08-17	8435 6065 11			

3	-	New connector: Motor & Transducer replaced = MK2	2013-03-06	ASH
Note	Pos.	Modified from	Date	Intr.

[illegible]

3	-	New connector: Motor & Transducer replaced = MK2	2013-03-06	ASH
Note	Pos.	Modified from	Date	Intr.

