





* FOR GREASE INSTRUCTION SEE PZ4113


SP= Specially designed part. Not available as standard spare part.

Max torque 90 Nm. Max speed 650 rpm.

10	0211 1170 00	2	HEX SOCK SCREW	MC6S M4x10 12.9	
9	4232 5886 00	1	CABLE RAIL	QST50 COT	SP
8	0211 1965 27	2	HEX SOCK SCREW	MC6S M4x18 H 12.9	
7	4230 2645 10	1	CABLE RAIL	QST 50	
6	4230 2127 00	1	SOCKET HOLDER	1/2" ±0mm 3" travel QM5 thru hole	
5	4230 1480 00	1	GREASE	KERNITE Lubra K HS*	
4	4232 7106 00	1	COMPRESSION SPRING	40-80N, TRA.76	SP
3	4232 5885 80	1	OFFSET GEAR	QDOT50-100-T76	SP
2	4230 2171 80	1	GEAR UNIT	ETX50 '50' : i=18.21= (((36/14)+1)•((41/10)+1)))	
1	4230 3012 80	1	MOTOR	QST 50	
Pos	Designation	Number	Name	Comment	Class
Tolerances, if not indicated, according to:					
AC-STD					
Name QST50-90COT-T76-L170-H13 QST					
Material -					
-					
Scale 1:2 Format A3 Family MK2 Compare -					
Drawn H Petrén Blank - Replaces -					
Cons.class 1295 K/- Rev 0 Status Released Designation 9831 4107 93					
Transferred from - Mass/Volume 8.6 kg Date 2018-01-11					
Drawing owner T00					
Sheet 1 (2)					

Rev. Ver 01

0	-	-	-	-
Note	Pos.	Modified from	Date	Intr.



Atlas Copco	Scale 1:2	Format A3	Family MK2	Compare -	Drawing owner
	Drawn H Petrén		Blank -	Replaces -	T00
Transferred from -	Cons.class 1295 K/-	Rev 0	Status Released	Designation 9831 4107 93	Sheet 2 (2)
	Mass/Volume 8.6 kg		Date 2018-01-11		